



**NATIONAL GUARD BUREAU**  
111 SOUTH GEORGE MASON DRIVE  
ARLINGTON VA 22204-1373

January 9, 2019

Mr. Colin Mitchell  
Alabama Department of Environmental Management  
1400 Coliseum Blvd.  
Montgomery, Alabama 36130-1463

Dear Mr. Mitchell,

I have enclosed for your review two hard copies, with CDs included, of the Supplemental Data Gap Investigation and Groundwater Monitoring Report for the Alabama Army National Guard (ALARNG) Organizational Maintenance Shop (OMS) #28 Mobile, Alabama.

The report documents the results of the soil and groundwater sampling and contaminant source refinement associated with the remedial efforts at the ALARNG Organizational Maintenance Shop #28 in Mobile, Alabama. The report provides information that identifies contaminant source areas in soil and refines the groundwater contaminant plume boundaries presented in the Alabama Department of Environmental Management (ADEM) approved Feasibility Study (FS).

If you have any questions or require assistance, please contact me at (703) 607-7589, david.m.connolly8.civ@mail.mil or Mr. Bradley Curvin at (334) 523-4027, bradley.n.curvin.nfg@mail.mil.

Sincerely,

 Date: 2019.01.09  
15:20:46 -05'00'

David Connolly  
Project Manager,  
Installations & Environment – Cleanup Branch

Enclosure

cc:  
Bradley Curvin, Alabama Army National Guard  
Melissa Shirley, U.S. Army Corps of Engineers, Mobile District