



NATIONAL GUARD BUREAU
111 SOUTH GEORGE MASON DRIVE
ARLINGTON VA 22204-1373

March 15, 2019

Installations & Environment – Cleanup Branch

Mr. Colin Mitchell
Alabama Department of Environmental Management
1400 Coliseum Blvd.
Montgomery, Alabama 36130-1463

Dear Mr. Mitchell,

I have enclosed for your review two hard copies, with CDs included, of the Risk Assessment Report for the Alabama Army National Guard (ALARNG) Organizational Maintenance Shop (OMS) #28 Mobile, Alabama.

The report documents the risk assessment prepared using the results of the soil and groundwater sampling provided in the Supplemental Data Gap Investigation and Groundwater Monitoring Report (January 2019). The report presents the assessment of the risk associated with the contaminant source areas in soil and the groundwater contaminant plume boundaries presented in the Alabama Department of Environmental Management (ADEM) approved Feasibility Study (FS).

If you have any questions or require assistance, please contact me at (703) 607-7589, david.m.connolly8.civ@mail.mil or Mr. Bradley Curvin at (334) 523-4027, bradley.n.curvin.nfg@mail.mil.

Sincerely,

A handwritten signature in blue ink that reads "David Connolly".

Date: 2019.03.15
13:10:17 -04'00'

David Connolly
Project Manager,
Installations & Environment - Cleanup Branch